


Appendix 4: Survival of Original Architectural Details in Jericho


Ordnance Survey maps produced under license 100019348



Houses where original window openings have been altered




- Less than 10%
- 11%-20%
- 21%-29%
- 30%-39%
- 40%-49%
- More than 50%



Houses with original doors or sympathetic replacements




-  Over 90%
-  80%-89%
-  70%-79%
-  60%-69%
-  50%-59%
-  Less than 50%




Houses where original door openings have been altered




- Less than 10%
- 11%-20%
- 21%-29%
- 30%-39%
- 40%-49%
- More than 50%



Houses where roof-lights have been inserted in to the front roof elevation



- Less than 10%
- 11%-20%
- 21%-29%
- 30%-39%
- 40%-49%
- More than 50%



Houses where original brickwork frontages have been painted or rendered



- Less than 10%
- 11%-20%
- 21%-29%
- 30%-39%
- 40%-49%
- More than 50%

